


PLAN VIEW



PROFILE VIEW

NOTES:

1. BACKFILL TRENCH WITH B-BORROW
COMPACTED TO 95% MODIFIED PROCTOR
2. SEE ROADWAY PATCH DETAILS FOR
REQUIREMENTS TO REPAIR ROADWAY

RETIREMENT OF CLAY SEWER LATERAL

NOT TO SCALE